


2 and 3 Axis Fixture Vises Welders Angle Clamps

2-AXIS WELDERS ANGLE CLAMPS

Made with machined cast iron. Featuring these improvements:

- WAC35D and WAC45 have Machined outside faces - usable for upright joint
- Stand-off increases access
- Quick acting screw on deluxe models



3-AXIS WELDERS ANGLE CLAMPS

Holds a 3-axis workpiece in position before welding. Features the QUICK ACTING SCREWS and "SWING AWAY" Arm.

Hold parts in position during cool down to minimize distortion due to contraction.



2 Magnetic Rest Blocks to support & level long stock!

FREE with models:
WAC35D, WAC45, and
3-Axis Fixture Vises:
WAC35-SW, WAC45-SW.



	Part No.	Features					A (mm)	B (mm)	C (mm)	D (mm)	E (mm)	F (mm)	H (mm)	Weight (kg)
		Quick Acting Screw	2x Stand-offs	2x Magnetic Rest Blocks	Swing Away Arm	Machined on Outside Faces								
2-Axis	WAC22		✓			✓	35.5	11	83.5	80	47	33	-	2.8
	WAC34		✓				40	11	95	107	64	35	-	4.3
	WAC35D	✓	✓	✓		✓	40	11	95	107	64	35	-	4.5
	WAC45	✓	✓	✓		✓	51	11	125	135	103	64	-	10
3-Axis	WAC35-SW	✓	✓	✓	✓		42	11	95	120	64	36	210	11
	WAC45-SW	✓	✓	✓	✓		51	11	125	135	103	64	245	16